

## **EPA RCRA Inspection Photos**

### **Clean Harbors Los Angeles**

**October 28, 2014**

**Prepared by Sharon Lin**

<b>Photos</b>	<b>Description</b>
1584	Bucket in a storage shed on site
1585	Storage shed
1586	Concrete floor
1587	Open bucket
1588	Open bucket
1589	Wastewater treatment plant Unit WMU-5
1590	Open container of universal waste
1591	Close up of 1590
1592	Container storage area B
1593	Used transformer at container storage area B
1594	Stain at the container storage area B
1595	Shed at the container storage area B
1596	Closer view of photo 1595
1597	Universal waste in open container in the shed
1598	Open bucket
1599	View of the container storage area B
1600	Used transformers at the container storage area
1601	Concrete floor at the container storage area
1602	Hazardous waste drum in container storage warehouse WMU-1
1603	Close up of picture 1602
1604	Hazardous waste drum in WMU-1
1605	Close up of picture 1604
1606	Hazardous waste drums in WMU-1
1607	Close up of picture 1606
1608	Different angle of picture 1606
1609	Drum in WMU-1
1610	Hazardous waste drum in WMU-1
1611	Close up of picture 1610
1612	Drum in WMU-1
1613	Drum in WMU-1
1614	Container holding universal waste in WMU-1
1615	Close up of picture 1614
1616	Container holding universal waste in WMU-1
1617	Clean Harbors LA administration building



SAM\_1584.JPG



SAM\_1585.JPG



SAM\_1586.JPG



SAM\_1587.JPG



SAM\_1588.JPG



SAM\_1589.JPG



SAM\_1590.JPG



SAM\_1591.JPG



SAM\_1592.JPG



SAM\_1593.JPG



SAM\_1594.JPG



SAM\_1595.JPG



SAM\_1596.JPG



SAM\_1597.JPG



SAM\_1598.JPG



SAM\_1599.JPG



SAM\_1600.JPG



SAM\_1601.JPG



SAM\_1602.JPG



SAM\_1603.JPG



SAM\_1604.JPG



SAM\_1605.JPG



SAM\_1606.JPG



SAM\_1607.JPG



SAM\_1608.JPG



SAM\_1609.JPG



SAM\_1610.JPG



SAM\_1611.JPG



SAM\_1612.JPG



SAM\_1613.JPG



SAM\_1614.JPG



SAM\_1615.JPG



SAM\_1616.JPG



SAM\_1617.JPG